NEENAH COLDENHOVE
Heat Transfer Paper

LASER
HEAT TRANSFER PAPER

For commercial use

Produced with: LASER-1-OPAQUE®

LASER-1-OPAQUE® Brand

For transfer to all **DARK** fabrics, mousepads, coasters, puzzles, leather, and other goods.

LASER-1-OPAQUE® Heat Transfer Paper is easy to use for transferring laser photo-quality images or other graphics to dark colored materials, offering a soft, supple transferred image that is vibrant and durable – and will withstand many laundry cycles, regardless of the model of laser printer or copier.

- Image can be plot cut or trimmed
- Image should be printed RIGHT-READING

HEAT
RIGHT-READING

NEENAH COLDENHOVE Brands for Laser Printers	Product ID	Natural & 50/50 Fabric	Poly Fabric	Hard Surface	Mesh Screen 85-230	Works well with Photos	Certified for HP Indigo Presses	Prepress*	Peel Temperature				Cover with Parchment	Repress and Stretch	Weedable
									Hot	Warm	Cold	Hand Iron			
TECHNI-PRINT® EZP	9868P0	✔	★	★		✔	✔	✔	✔	✔	✔	✔	●	●	★
PHOTO-TRANS SC®	0908P0	✔	★	★		✔	✔	✔	✔						
IMAGE CLIP® Laser Light	9770P0	✔	★	★			✔	✔	✔ 1st		✔ 2nd				✔ Self
TECHNI-PRINT® HS	9842P0			✔		✔	✔				✔				★

✔ Yes   [✔ If, ● Then]   ★ With special settings, dictated by the design   *Prepress to remove wrinkles and moisture.

OKI
SUPPORTED

MADE IN USA

To order this product, please visit Specialty Graphics Supply at www.Specialty-Graphics.com.

PRINTING INSTRUCTIONS:

1. Print image right reading.
2. Trim away the unprinted areas of the transfer if desired.

> Press Settings should be 350°F/177°C with medium to heavy pressure for 30 seconds

PRE-TRANSFERRING INSTRUCTIONS:

1. Prepare the garment/fabric by ensuring the surface is clean, dry, and wrinkle free by using a lint brush and your heat press.

TRANSFERRING INSTRUCTIONS:

1. Bend a corner to remove the backing paper from the printed image.
2. Place the printed image on top of the garment with the image facing up (right-reading to you).
3. Completely cover the image with siliconized parchment paper.
4. Press 30 seconds at 350°F/177°C using medium (30 psi/2 to 3 bar) pressure.
5. Peel the parchment paper off in a smooth even motion after the transfer cools completely.

WASHING INSTRUCTIONS:

Turn garment inside out and wash in cold water using a mild detergent. Do not use bleach. Dry on low-heat setting.
If you intend to iron the transferred area, ensure that the image is covered with parchment paper before ironing.

IMPORTANT: Printers and heat presses vary in accuracy. We have tested our products with numerous printers and presses with excellent results. Nonetheless, we recommend that you test the paper in your equipment to ensure the best results. Neenah's maximum obligation shall be to replace any paper that has proven to be defective.

NEENAH COLDENHOVE
Heat Transfer Paper

MORE THAN 50%
MADE FROM RENEWABLE RESOURCES

For more information about Neenah Paper Heat Transfer Papers:
North America: 800.344.5287 | **Outside North America:** 906.387.2700
neenahheat.com | neenah.heat@neenah.com | @neenahheat

NEENAH CONTROLS THE PROCESS
"FROM TREE TO T"™