## Materials

Cotton,	polyester	and cotton/	poly blends
---------	-----------	-------------	-------------

mperature		
5°F - 325°F		
ne		
10 seconds		
essure		
edium to high, even pressure (20 to 30# PSI)		
el		
el hot, warm, or cold		
portant Notes:		
Adjust time, temp and pressure as needed based on the textile/substrate. Use higher temperature range for cotton and the lower temperature range for polyester and synthetic textiles. A post press of approx. 10-15 seconds with parchment paper is highly recommended for improved adhesion, durability, and washability. To produce a glossy finish, use a PTFE non-stick sheet for the post press instead of the parchment paper.		

Care

Machine wash warm with mild detergent. Dry at normal setting. No chlorine bleach.

Note: Because of the wide variety of fabrics and garment manufacturers that exist, we highly recommend that this product be fully tested prior to going into production.